



# Stella Doradus Ireland Ltd.

## Assembly Instructions Planar Tilt

Part Checklist	
4 x Clamp Brackets	4x long M6 bolts
4 x Ear Bracket	10x short M6 bolts
2 x side bars	4x M6 nuts
	10x M6 wing nuts
	4 x M6 washers

